

www.dewesoft.com - Copyright © 2000 - 2025 Dewesoft d.o.o., all rights reserved.

## **Orbit analysis**



### Training course summary

In this course you will learn the basics of how to set-up and use Orbit analysis, and how to interpret the analysis results.

The course will also include data examples and the main theory behind the calculations, and in the end you should have gathered enough information to be able to get started using the application yourself.

As for all DEWESoft courses, this course is completed with a quiz. The quiz will have questions for which the answers can be found in the course material.

### Why should you use Orbit Analysis?

Having a steady, continuous operation with as few malfunctions and vibrations as possible is essential for maximizing productivity and ensuring the reliable operation of a machine - whether a huge rotating mass in a power plant or a high-revving compressor. Knowing the rotor movement, then different phenomena of lubrication and bearing states can be determined and consequently, machine operations can be optimized.

To achieve this, measurement and analysis of rotational vibration data is crucial. Dewesoft Orbit analysis is an ideal analysis tool for rotor dynamic movement examination, assessment of any motion restrictions causing vibration, and consequent prevention of potential, unwanted damages to rotating machinery that would result in premature wear of components and could cause critical failure.

Orbit analysis can monitor and analyze the current state of journal bearings and how such bearings have behaved over time while in operation.

Orbit analysis is designed specifically for such bearing types to inspect and diagnose shaft / journal movement, the oil lubrication, and the clearance.



Dedicated display widgets for orbit analysis helps create a clear overview of the state of one or multiple bearings. Such analysis is crucial to understand the impact of the lubrication oil, the shaft load, the rotation speed, the clearance, and the wear and tear of bearing.



### When should you use Orbit Analysis?

Orbit analysis is applicable for analysis of journal bearings. Journal bearings are also sometimes referred to as bushings, plain bearings, or sleeve bearings. These bearing types all have a fluid lubrication layer in between the shaft and bearing which makes the shaft have a sliding action with a loose movement within the clearance.

Orbit analysis is not applicable for roller bearings and gears, or other bearing types having roller action or direct connection between the shaft and bearing, since you do not have a fluid medium / lubrication in between, and hereby no loose shaft movement. Instead, for such direct contact bearings and gears Order analysis is the proper application.

# What is needed to configure and get going with Orbit Analysis?

The basic measurement setup for orbit analysis consists of:

- pair of proximity probes (also called eddy-current probes) per bearing,
- a keyphasor (3rd proximity probe or a tacho sensor),
- a data acquisition system,

- orbit analysis software,
- and a computer.

By detecting the shaft proximity in two directions (x and y) rotor movement is calculated and displayed throughout the measurement.

### Orbit analysis system configuration

Dewesoft Orbit Analysis system is very flexible and can be configured for single or multiple bearing measurements at the same time. The input channel count can be expanded at any time. DAQ system can also be configured to allow different sensor connections at the same time - thermocouples, RTDs, IEPE/ICP® accelerometers, strain gauges, and more.

A typical Orbit analysis measurement system can consist of the following elements:

- SIRIUSi isolated data acquisition system with 8xLV signal amplifiers or 6xLV-2xLV+ (additional two counter) amplifiers.
- 2-8x Eddy-current probes
- DewesoftX Orbit Analysis option

#### **Optional:**

Extra software tools that can extent the monitoring and analysis capabilities around Orbit analysis:

- FFT Analyzer option
- Order tracking analysis option
- Rotor balancing option
- OPC UA Client/Server option
- Historian time-series database
- MODBUS protocol option



### Industry case examples

Orbit analysis is one of the main diagnostics tools for rotating machinery using journal bearings, such as turbomachinery. Turbomachinery provides kinetic energy to operations enabling movement - a function that is widely used in industrial processes to move solids, liquids, or gases through drivers, driven components, and transmissions such as:

- Compressors
- Drills
- Generators
- Turbines
- Engines
- Pumps
- Blowers



Such rotating machinery as shown above is applied in a variety of industries, e.g. automotive, chemical, oil and gas, metals, HVAC or mining, and in the majority of different power plants:

- Hydroelectric
- Nuclear
- Thermal
- Gas
- Coal
- Biomass

Below is an example that shows how a journal bearing is monitored at a hydropower plant. By monitoring the shaft centerline position together with both orbit plots, polar plots, shaft speed, and much more, it is possible for the operator to follow the bearing condition, both regarding bearing wear and tear, but also regarding e.g. lubrication oil conditions.



### Proximity probe

A proximity sensor is able to detect a nearby object without making contact with it, and then output a pulse or voltage signal.

From the mounting point, they measure both the static dc displacement and the dynamic variating displacement behavior of the moving machinery.

Eddy current proximity probes normally consists of the probe itself, a driver, and a regulated DC supply. Proximity probe drivers usually require a DC supply input of -24 VDC. The driver outputs a high-frequency signal to the probe coil. The coil generates a magnetic field into the surrounding area. If a conductive material intercepts the magnetic field, eddy currents are generated and the high-frequency signal loses power. The closer the conductive material is to the probe tip, the more power the signal loses. This power loss triggers a change in the voltage of the driver.

The required DC supply of -24 VDC is supported by specific DEWESoft DAQ device types. These devises are:

- SIRIUS LV
- IOLITE LVe
- IOLITE STG

By using one of of the above listed modules most proximity probes can be excited directly from the DEWESoft DAQ without requiring extra DC supply power.



There are several types of proximity sensors, which are chosen based on the composition of the object(s) that should be detected.

For example, an inductive proximity sensor creates an electromagnetic field around its measuring end. According to the well-known magneto-resistive effect, the resistance of certain objects (particularly ferrous ones) will change when they are exposed to magnetic fields. Most proximity sensors take advantage of this effect by creating a small magnetic field and then detecting when it is interrupted or changed significantly due to the presence of such material.

So when we place such a sensor near a rotating shaft and then affix a ferrous feature onto the shaft that will pass close to the sensor with each revolution, we have a very reliable and accurate speed sensor. The sensor detects the field



There are also capacitive proximity sensors that can detect non-metallic objects, using the principle of capacitive coupling. Instead of an electromagnetic field, they generate an electrostatic field. As an object enters this field it changes the capacitance in the sensorâ€<sup>™</sup>s oscillator circuit. This is detected by the sensor which then creates an output. In the case of both magnetic and capacitive proximity sensors, their sensitivity to the target object can be adjusted.

#### Proximity sensor pros:

- Very reliable because they never make contact with the objects being detected. Wear and tear are virtually nonexistent
- Very low initial and operating cost
- Capacitive types can also be used to measure the thickness
- Inductive types are not affected by water, mud, etc.

#### **Proximity sensor cons**

- Limited detection distances most inductive sensors are limited to 70mm (2.76 in.)
- They require external power

### Analog Input setup - proximity probes

Under the 'Analog in' setup tab, displacement channels need to be configured properly to be used as proximity probes.

Most often orbit analysis configurations consist of two eddy-current probes per bearing for Y and X direction displacement detection. In addition, one or more bearings might have a third proximity probe mounted used as the phase reference key-phasor channel, which notify each time the shaft has rotated a new full revolution.

Depending on whether the utilized eddy-current probes use a separate signal conditioner or are connected directly to the input on DEWESoft HW, different amplifiers are used.

For both cases, Voltage mode is selected under Measurement and Displacement/distance as a Physical quantity.



If the proximity probes should be conditioned/excited directly by DEWESoft DAQ devices, then remember to use one of the device types that can output enough excitation voltage, for example like SIRIUS LV, IOLITE LVe or IOLITE STG.

In such cases set the DAQ device to output the required excitation voltage to the probe drivers:

Amplifier - DEI	MO-SIRIUS-LVv2			Sensor
General Info	Connector			
Measurement	Voltage ~			
Range	200 V V Dual core	eΎV		TE
Low-pass filter	Anti-aliasing filter (IIR) $\sim$		In+ (2)	(+) <sub>Ou</sub>
Coupling	DC v		In- (/)	(-)
Input type	Differential ~			
Excitation	24 ~ V ~		Exc+ (1)	
Excitation type	Unipolar ~		Sns+ (6)	Pot
Amplifier	Short on	t	Sns- (3)	- + -
			Gnd (4)	
		•	¥	

Note that some probe drivers require the excitation voltage to be negative, so the output Exc +/- wirings might have to be switched.

### Orbit analysis setup - add module to setup

The orbit analysis application module can be added to a setup by pressing the "+ More..." button and then selecting Orbit Analysis:

			_				
	Measure	Anal	lyze Setup f	files Ch. setup Me	asure		
0	B	F		<b>₩</b> #±	+ -		
Store	Save	Save as	s Storing	Analog in Math	More Remove		
Dynami	c acquisitio	n rate	Channel act	tions	<u>م</u>	Add module New setup defaults	
5000	~	Bandwidth: 1953 Hz	Balar	nce amplifiers Short on	General	((🌲)) Alarms	Strain, stress
(Hz)					Channels	🗖 Video 🗙	Fatigue analysis
Search		٩	r 🗸		Storing	Security	Electrical measurements
ID	Used	Stored C	C Sample rate	Name	📕 Data header 🛛 🗙	👆 User inputs	F Aircraft Power AC
1	Used	Store	5000	AI 1	System monitor	Cursor	Power analysis
2	Unused	Not s	5000	AI 2	r 品 NET 🛛 🗙	Frequency domain analysis	Acoustics
3	Unused	Not s	5000	AI 3	M Analog in	FFT analysis	Microphone Correction
4	Unused	Not s	5000	AI 4	E Function generator	Machinery diagnostics	RT60
5	Unused	Not s	5000	AI 5	010001 CAN	🍐 Combustion engine analysis 🛛 🗙	🐠 😯 Sound level meter
6	Unused	Not s	5000	AI 6	Counters	(😫)) Human vibration	Sound Quality
7	Unused	Not s	5000	AI 7	Mul Analog/digital out	Orbit Analysis 📐 🗙	Real-time controllers (RTCs)
8	Unused	Not s	5000	AI 8	💉 gps 🗙	Order tracking 😽 🗙	Triggers out RT
9	Unused	Not s	5000	AI 9	🞵 Digital in	🛞 Rotor balancer 🛛 🗙	M Analog output RT
10	Unused	Not s	5000	AI 10	1 Markers		CAN output RT
11	Unused	Not s	5000	AI 11	, πż Math		XCP output RT
12	Unused	Not s	5000	AI 12	-		
13	Unused	Not s	5000	AI 13	Orbit Analysis 1.0.0 Precise rotor movement measurements and adv	anced analysis tailored for turbomachinery applica	tions
	1111.35.1	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1				and a second carbon carbon a contractificity applied	

#### When adding the module the following module setup appears:

Channels Events Math OA More Remove							
OA 1 +							
Frequency channel setup  Frequency source  Frequency channel  Analog pulses  K  BDM setun	Sensor Tacho (Analog) Tacho Calculation ceture	Lower 1	frequency limit	Channel setup Buffer size	) min		
Direction Both Delta RPM So Direction control Direction control Mode Master	Harmonic list     FFT w       0;1;2;4;8     Hann       Order resolution     Amplii       1/8 (0.125)     Peak       Max order to analyse     Frequ       32     Hz       Time FFT lines     Auto       Auto     df = 4       Bin update     Average	vindow tude c uency axis unit 3,05 Hz, duration = ( eparate spectra per c	Update V O V Waterfa Orde Orde V FFT V Overall Ove	interval n time 2 n n RPM change (Delta alls r waterfall vs. RPM r waterfall vs. time waterfall vs. RPM vs. RPM vs. sak eak-peak	min 0 s IRPM) Single sided Two si V V	ded ⊻Tir ✓Or	ne DC cutoff der DC cutoff
Runout compensation         DC value is subtracted from runout con           10         1         •         Runout corrections or reference orbit a by lockable cursors.	ections. A re calculated from interval defined	eterence orbit Averages Lock 10 Run Reference orbit avera	able cursor calculatic out compensation aging requires stead	n V RPM.			
Machine configuration							
+ C Measurement point Configu Rotation	Channel	Angle	Position	DC gap	Measure DC gap	Setup	
•         •	Y X	45,00 45,00	Left Right	0	Measure Measure	Setup	

The module setup UI is divided and described in the following sections:

- Frequency channel setup
- RPM setup
- Calculation setup
- Runout compensation
- Reference orbit
- Machine configuration

As all other module, Orbit analysis can be added to a setup both in Measure mode and in Analyze mode, but this module will typically be used in Measure mode and therefore added here.

Note that the Orbit analysis module requires a license referred to as 'DEWESOFT-X-ORBIT-ANALYZER', else it might not be visible or selectable.

### Orbit analysis setup - frequency channel setup

To determine the shaft rotation speed and angle, you need to configure a channel providing rotation frequency data. For Orbit analysis, a third proximity probe also called a keyphasor is most often used as it detects a flat or wedged section on the shaft and this generates the needed pulse per revolution from which operating speed and angle is concluded.

To allow different configuration possibilities to the user, the Orbit Analysis module supports several different sensor types to be selected as the frequency source:

	requency channel setup				
	Frequency source	Frequency channel	Sensor		Lower frequency limit
	Analog pulses 🗸 🗸	к	<ul> <li>Tacho (Analog)</li> </ul>	×	5 Hz
	Counters Counter math		Tacho		
R	Analog pulses		Calculation setup		
	KPM Channel				

#### Counters

With Orbit Analysis, detection of several pulses or transient spikes per revolution can be used by selecting one of the sensor types supporting this after a counter channel has been selected as the frequency source.

								÷
Frequency channel setup								
Frequency source	Counter cha	nnel	S	ensor		Filter		
Counters	V CNT1		~ 1	Tacho (Digital)	~ .	500 ns	$\sim$	
			E	Encoder-1800 Encoder-3600	^			
RPM setup			Calculation s	CDM-360				
Direction		Upper RPM limit	Harmonic lis	Tacho (Digital)	w			ι
Runup 🗸	REF	3000	0;1;2 E	Encoder -256 Tape sensor		×	/	

For multiple configuration possibilities, a variety of additional counter sensors are available in the dropdown: multiple Encoders as well as CDM sensors. In addition, different filter settings can be applied to selected frequency source signals.

#### **Counter math**

With the Counter math module it is possible to determine and recalculate counter angle- and frequency outputs while measuring, online, and during datafile analysis after a measurement, offline.

This can be useful when you e.g. want to fix a faulty counter setting that wasn't caught during the measurement, or if you want to tune a setting or two to see if that produces better results.

Remember to store the "Raw edge separation†and "Raw count†channels during the measurements, since such data is required to perform the recalculation.

Counter math supports features like frequency smoothing, teeth size adjustment, software filters, and angle wrapping.

If the results from Counter math turn out to be better for your specific data file, you can also use the math output as input to other modules that work with counters, such as Orbit analysis, Order Tracking or Torsional Vibration.

Frequency channel setup	
Frequency source	Counter channel
Counter math $\checkmark$	CNT1 ~
RPM setup	🔺 Counter math setup
Direction	Sensor
Runup V	Same sensor as counter Sensor
Delta RPM	Tacho (Digital) 🗸 🗸
50	Calculations
	Angle output Input filter
	Frequency output 0 (HW only) v ms
	Angle settings
	Angle unit Angle wrapping Zero offset
	revs 🗸 Auto (wrap) V 0
	Frequency settings Lowest frequency
Runout compensation	Frequency unit Freq. interpolation Lower frequency limit
Averages Resolution	Hz ~ Hold ~ Auto (0,500) ~ Hz
10 1	Frequency drop time
Apply runout compensation	0s
Warning: Analog or counter tac	

#### Analog pulses

When having the Frequency source set to Analog pulses an analog time channel must be selected (different sensors generating analog pulses are supported).

Frequency channel setu	Р				
Frequency source		Frequency channel		Sensor	
Analog pulses	~	Keyphasor	~	60-2 (Analog)	
				60-2 (Analog)	-
				36-2 (Analog)	
RPM setup			Calculation	E Tacho (Analog/	

- Tacho(Analog): 1 pulse per revolution using a proximity probe or a similar type of analog sensor
- 36-2 (Analog) or 60-2 (Analog): sensor with 58 or 34 teeth and two missing teeth

To configure the selected Analog sensor, click on the three-dot icon to open the Angle sensor math setup.

In the Angle sensor math setup, additional settings are available to configure the sensor:



- Trigger edge
- Trigger level (can also be found automatically by selecting ''Find''),
- Retrigger level,
- Retrigger time,
- Output channel unit (Hz or RPM) and
- Averaging
- a preview of analog tacho signals and triggers.

The Lowest detectable frequency limit is definable in the user input field - the system will not detect frequencies lower than the specified value.

#### **RPM channel**

Besides analog and digital sensors, any signal or channel directly representing the RPM (e.g. 0-10V equals 0-4500 rpm) can be used as a frequency source. As this option does not contain zero-angle information the extraction of phase is not possible.

### Orbit analysis setup - RPM setup

Under the RPM setup section, Lower and Upper RPM limits are defined as well as Delta RPM width and the direction of the test.



To configure the analysis according to the test conditions of the particular rotating machinery during the measurement and to get all of the needed data RPM setup section includes the necessary settings that apply to the direction, speed range of operation as well as the density of calculation of values during the test run.

#### Direction

Orbit analysis supports the measurement of different machine operation scenarios: whether only the runup, coastdown, or both need to be measured, the analysis is easily configured accordingly via a dedicated dropdown.

As turbomachinery often runs for long periods in steady state conditions between the runup and coastdown, selecting Both in the dropdown will automatically create a third operating condition as well: Steady-state. Each Direction creates a dedicated set of channels for the display of measured data so they can be displayed on separate widgets or all together on the same one for comparison.

The user controls the current state of operation during the measurement via a dedicated dropdown which is automatically put on the predefined display. More information on this control dropdown can be found in the later sections of this manual covering Measurement & Visualization.

#### Delta RPM

Delta RPM defines the change of speed at which data is updated during the measurement for the speed channel and all Orbit Analysis output channels containing speed information: Filtered orbit(e.g. Orbit H1), Shaft centerline, Polar plot, Order Waterfall vs. RPM and FFT waterfall vs. RPM

For example, a delta RPM of 50 will update the channels each time during the runup or coastdown the speed of the machine changes for 50 RPM.

During steady-state operation conditions, the speed of the machine usually varies very little. This means that the delta RPM criterion will not be fulfilled and the update of measured data on affected channels will not be triggered. That is why Orbit Analysis can be also updated on time or both (whichever is true first), More info on how to configure update on time criteria can be found in the following section.

Lower and upper RPM limits

Upper and Lower RPM limits define the range for calculation and are used to correctly set up the resampling algorithm, depending on the max order extracted. They should be set by the expected speed range of the machine being measured:

### Direction control

This makes it possible to control the Direction under Measure for multiple Orbit Analysis modules at the same time. In setups with multiple added Orbit Analysis modules and at the same time using the Direction Both, you can select to link the Direction control together instead of having to change the Direction for each module individually.

The Mode parameter can be set to Master or Client. For Clients, you must select which Master it should be linked to.

For example, if module OA1 is Master and module OA2 is a client to OA1, then this two modules are linked and Direction changes under Measure for one of them will also apply the same change to the other one:

OA 1 OA 2 +				
Frequency channel setup	p			
Frequency source	Frequency channel	l	Senso	r
Analog pulses	~ к		✓ Tacho	(Digital)
RPM setup			Calculation setup	
Direction		Upper RPM limit	Harmonic list	
Both 🗸		3000	0;1;2	
Delta RPM	[	Lower RPM limit	Order resolution	
50		0	1/8 (0.125)	~
			Max order to ana	yse
Direction control			32	~
Mode	Master module		Time FFT lines	
Client	✓ OA 1	~	Auto	~
			Bin update	
			Average	~

### Harmonic list

The extraction of desired filtered orbits is configured by inputting the order numbers in the harmonic list field, separating the entries in the list with a semicolon (;). In the below example, the first, second, and third harmonic orbits are extracted.

Calculation setup		
Harmonic list		FFT window
Order resolution		Amplitude
Order resolution		Ampitude
1/8 (0.125)	$\sim$	Peak 🗸
Max order to analyse		Frequency axis unit
32	$\sim$	Hz 🗸
Time FFT lines		
Auto	$\sim$	df = 3,05 Hz, duration = 0,33 s
Bin update		
Average	$\sim$	Separate spectra per direction

### Order resolution

Selected order resolution defines the steps on the order waterfall between individual extracted orders. The higher the resolution the higher the number of lines between the orders.

Calculation setup	
Harmonic list 0;1;2	FFT window Hanning ~
Order resolution 1/8 (0.125)	Amplitude Peak ~
1 1/2 (0.5) 1/4 (0.25)	Frequency axis unit
1/8 (0.125) 1/16 (0.06) 1/32 (0.03) 1/64 (0.015)	df = 3,05 Hz, duration = 0,33 s
Average ~	Separate spectra per direction

In an FFT, if the line resolution is 0.5 Hz, the required data window must be 2s. The same is true for the ordered resolution: If the resolution is set to 0,25 orders, 4 revolutions are required for one data block. The higher the required order resolution, the slower the rpm must change.

In an FFT, if the line resolution is 0.5 Hz, the required data window must be 2s. The same is true for the ordered resolution: If the resolution is set to 0,25 orders, 4 revolutions are required for one data block. The higher the required order resolution, the slower the rpm must change.

### Maximum order to analyze

Depending on the measurement application, the maximum order to analyze needs to be set high enough to still capture all

the wanted orders. If, for example, a higher number of orders are not needed in the analysis, a lower value can be selected from the dropdown to consequently lower the needed sample rate and the amount of data stored.

The needed sample rate is determined by the Orbit Analysis module using the following formula:

#### Upper RPM limit in [Hz] \* max order to analyze \*2 (Nyquist)

To cover 3600 RPM with 32 set as the highest order to analyze, the needed sample rate would be. 60 \* 32 \* 2 = 3840 Hz. By default, 32 is set as the highest order to analyze. As the orbit analysis utilizes parts of order tracking math to calculate the data, this setting needs to be configured also in Options->Settings->Extensions->Order tracking. The system will take the highest of the two settings into account.

#### **Time FFT lines**

Affects the FFT cascade output, a higher number of lines results in better resolution and higher CPU load (supports Auto, predefined values selection from dropdown or arbitrary definition of a number of lines.)

#### Bin update

Bin update is used to define how the output data for each RPM speed bin is calculated.

- Always When multiple values or spectra belong to the same bin, then the newest bin values will overwrite previous values and the newest values will be used in the output for that bin.
- First time When multiple values or spectra belong to the same bin, then only the first bin values will be used in the output for that bin.
- Average When multiple values or spectra belong to the same bin, then averaging for the values and individual and spectral lines will be performed over all values belonging to that bin.
- Maximum When multiple values or spectra belong to the same bin, then the maximum value for all values and individual spectral lines across all spectra belonging to that bin will be kept.

#### **FFT** window

Different windows are available for the FFT:

- Rectangular,
- Hanning,
- Hamming,
- Flat top,
- Triangle,
- Blackman (selected by default),
- Exponential down and
- Blackman Harris.

#### Amplitude

Depending on the selected amplitude in the dropdown, the following scaling is applied to the Bode plot and Polar plot: Peak, RMS, Peak-peak

#### Frequency axis unit

Frequency axis unit for FFT waterfall vs. RPM can be selected from the dropdown list.

Using CPM (cycles per minute) instead of RPM (revolutions per minute) for naming the units prevents confusion when showing FFT waterfall vs. RPM on the 3D graph. In this case, CPM is used on the frequency axis and RPM on the speed axis.

#### Separate spectra per direction

Separate spectra per direction will create the selected spectral channels under all Directions channel groups. When disabled the spectral results will be combined across all directions.

#### **Update interval**

Update interval defines the criteria on which data, such as speed, shaft centerline and polar will be updated during the measurement.

There are two different criteria for update of data:

- On RPM change (Delta RPM) data is updated each time a defined Delta RPM value is exceeded. This is usually selected if the measurement consists of runup or coastdown or both.
- On time Values are updated on a defined time interval, regardless of the Delta RPM specified. This update criterion is suitable for steady-state operating conditions when RPM change criteria are not going to be triggered. Both update criteria can be selected at the same time to appropriately cover different operating conditions.

A measured turbine is going to do a runup from 50 RPM to 4500 RPM, perform a steady state operation at maximum speed for hours and finish with a coastdown back to idle speed. The user inputs 50 as delta RPM, meaning data will be updated in 50 RPM intervals during runup and coastdown. During the steady state machine is running stable and the speed varies very little(+-10RPM) so Update on time is switched on as well and 10 minutes is defined as update time criteria. During hours of steady state operation, values are updated each 10 minutes, resulting in a good overview of the operation.

#### Orbit analysis waterfalls

The Orbit Analysis module supports Order waterfall spectrograms vs. RPM and vs time, and at the same time FFT waterfall vs, RPM.

They are enabled easily by ticking the checkbox in the Ch. setup section. They are shown using the 3D Graph widget which is further explained in the Measurement & Visualisation section

Vs. RPM spectra can be created both as Single-sided or Two-sided spectra. Single-sided spectra will have an order or frequency axis starting from 0. Two-sided spectra will have an order or frequency axis centered around 0.

Two-sided spectra can be of interest when analyzing the phase difference between the X and Y-bearing sensors.

#### **Overall vs. RPM**

Overall vs. RPM, results are 2D arrays with overall displacement levels across the defined RPM speed range. Such results can be a good way to overview and document critical speed intervals which should be avoided.

### Orbit analysis setup - Runout compensation

Runout compensation is performed to remove shaft irregularities from the measured values. In the Runout compensation section you define the number of Averages (revolutions) to be taken into the calculation, and the desired angle Resolution.

Runout compensation					
Averages Res 10 1 Apply runout cor	o pensation	DC value is subtracted from runout corrections. Runout corrections or reference orbit are calculated from interval defined by lockable cursors.			

Under Measure, the Orbit analysis module provides a display template design for the runout compensation measurement. When the runout Start button is pressed the runout measurement will start and the number of Averages will begin to count up.

The compensation is typically performed at low rotational speeds when the shaft is rotating slow enough for it to remain stationary (in regards to the movement inside the bearing clearance). However, not all rotating machinery is the same and some of the machines require compensation to be performed at higher speeds.

The Runout compensation values are calculated in the angle-domain. This means that you can perform runout compensation measurements while running with variable speeds.

Runout compensation and DC offset / Gab (explained under the Machine configuration section) are independent of one another.



### Orbit analysis setup - Reference orbit

Reference orbit is a great tool for easy comparison of current operating conditions to those from a previous measurement.

During the measurement, reference orbit can be easily acquired through a dedicated measurement screen.

The number of averages taken into the measurement is defined by the user in the Averages field.

Reference orb	it
Averages	Lockable cursor calculation
10	Reference orbit 🛛 🗸
Reference orb	Reference orbit

- Averages specifies how many times the deflections at individual angles are averaged together.
- Lockable cursor calculation Used when calculating runout compensations and reference orbits in Analyze mode (post-processing). Set this parameter to the desired calculation type to use the correct lockable cursors.

After measuring reference orbits the determined values can be illustrated under the Bearing Setup section after pressing the Paste button. The data will be added to the selected reference orbit table:

Reference orbit 3 $\sim$	Add	Remove	Paste	Import
Y		x		

Reference orbit measurements should be performed while maintaining a steady rotation speed.

### Orbit analysis setup - Machine configuration

Any number of bearings can be defined with Dewesoft OA into the machine train. Machine configuration setup can be further broken down into subsections:

Machine confi	Machine configuration										
$\odot$	Duplicate										
+ C.	Measurement point	Configu	Rotation		Channel	Angle	Position	DC gap	Measure DC gap	Setup	
4	Bearing 1	Pair	CW							Setup	3
	Y			1	Probe Y	45,00	Left	0	Measure		
•	X			- 1	Probe X	45,00	Right	0	Measure		
									2		

- 1. 1 Quick settings
- 2. 2 DC gap
- 3. 3 Bearing setup

### Quick settings

Under the Channel, the right input channels need to be assigned as probes X and Y for the individual bearing.

Machine confi	Machine configuration								
$\odot$	Duplicate								
+ C.	Measurement point	Configu	Rotation	Channel	Angle	Position	DC gap	Measure DC gap	Setup
4	Bearing 1	Pair	CW						Setup
	Y			Probe Y	45,00	Left	0	Measure	
	x			Probe X	45,00	Right	0	Measure	

Next, the angles and positions at which the probes are mounted need to be configured.

Machine con	Machine configuration								
$\odot$	Duplicate								
+ C.	Measurement point	Configu	Rotation	Channel	Angle	Position	DC gap	Measure DC gap	Setup
4	Bearing 1	Pair	CW						Setup
	Y			Probe Y	45,00	Left	0	Measure	
	X			Probe X	45,00	Right	0	Measure	

To make the configuration of the Angle and position easier, the graphical representation is available upon entering the Bearing setup

### DC gap

Most of the time when proximity probes are mounted, there will be a certain DC component present. Dewesoft Orbit Analysis supports easy measurement of the DC gap by clicking on the Measure button next to the individual probe.

uration								
Duplicate								
Measurement point	Configu	Rotation	Channel	Angle	Position	DC gap	Measure DC gap	Setup
Bearing 1	Pair	CW						Setup
Y			Probe Y	45,00	Left	0	Measure	
X			Probe X	45,00	Right	0	Measure	
	Uplicate Duplicate Measurement point Bearing 1 Y X	uration       Duplicate     Configu       Measurement point     Configu       Bearing 1     Pair       Y     X	uration           Duplicate         Configu         Rotation           Measurement point         Configu         Rotation           Bearing 1         Pair         CW           Y             X	uration           Duplicate         Configu         Rotation         Channel           Measurement point         Pair         CW            Y         CW         Probe Y           X         V         Probe X	uration           Duplicate         Configu         Rotation         Channel         Angle           Measurement point         Pair         CW           45,00            Y         Image: Circle Cir	uration           Duplicate         Configu         Rotation         Channel         Angle         Position           Measurement point         Pair         CW            Position <t< td=""><td>Measurement point         Rotation         Channel         Angle         Position         DC gap           Bearing 1         Pair         CW         C           Y         CM         C           Y         C         C           Y         C         C           Y         C         C           Y         C         C           Y         C         C           Y         C         C           Y         C         C           Y         C         C<!--</td--><td>Measurement point         Rotation         Angle         Position         Dec gap           Measurement point         Configu         Rotation         Channel         Angle         Position         DC gap         Measure DC gap           Bearing 1         Pair         CW         CW         CM         CM         Measure DC gap         Me</td></td></t<>	Measurement point         Rotation         Channel         Angle         Position         DC gap           Bearing 1         Pair         CW         C           Y         CM         C           Y         C         C           Y         C         C           Y         C         C           Y         C         C           Y         C         C           Y         C         C           Y         C         C           Y         C         C </td <td>Measurement point         Rotation         Angle         Position         Dec gap           Measurement point         Configu         Rotation         Channel         Angle         Position         DC gap         Measure DC gap           Bearing 1         Pair         CW         CW         CM         CM         Measure DC gap         Me</td>	Measurement point         Rotation         Angle         Position         Dec gap           Measurement point         Configu         Rotation         Channel         Angle         Position         DC gap         Measure DC gap           Bearing 1         Pair         CW         CW         CM         CM         Measure DC gap         Me

After the DC gap is measured, a value will be shown in the DC Gap column. DC Gap can also be input manually in the Bearing setup window as explained in the next section.

### Bearing setup

Upon selecting Setup under Machine configuration, a dedicated Bearing Setup window is opened, containing all of the advanced settings for configuration of the bearing settings:

- sensor configuration,
- subsynchronous orbit extraction,
- shaft and clearance circle configuration,
- average orbit definition, and
- DC gap manual input.

Inside this setup window, the user defines the runout compensation as well as the reference orbit.

Setup										×
Bearing properties										
Bearing name										
Bearing 1										
Sensors										
Configuration	Tacho angle		Γ							
Pair ~	Left vat 0	•	L	Runout compensation	on 🗸	Add	Remove	Paste	Import	Export
Y position	X position			Angle[°]		Y [-]			X [-]	^
Probe Y V	Probe X	~	[	0,00		0,00			0,00	_
Y angle	X angle			1,00		0,00			0,00	
Left v at 45 °	Right $\lor$ at 45	۰	-	2,00		0,00			0,00	
Left <sup>0°</sup>	Right		-	3,00		0,00			0,00	
	*		-	4,00		0,00			0,00	
<b>∀</b>	×		-	5,00		0,00			0,00	
			-	6,00		0,00			0,00	
			-	7,00		0,00			0,00	
			-	8.00		0.00			0.00	
			-	9.00		0.00			0.00	_
180°			-	10.00		0.00			0.00	_
Calculate subsynchronous or	bit		-	10,00		0,00			0,00	_
			-	11,00		0,00			0,00	_
HZ				12,00		0,00			0,00	~
Shaft		Clearance			DC	Gap				
Rotation Posit	ion	Shape	Radius	1	Se	nsor Y	Sen	sor X	1	
CW V Cen	ter 🗸	Circle ~	5	]-	0		- 0		-	
Average orbit		Channel colors								
Periods Averages		Runup	Steady sta	ate Coastdown						
3 4		-		•						
								ОК	С	ancel

#### **Bearing properties**

Under the Bearing name, a unique name can be input by the user to easily recognize which component it corresponds to.

#### Sensor

The graphical representation of the shaft together with direction and angle helps with the correct configuration of the sensor settings.

In this section, the user selects the configuration:

- · Pair is selected when two probes per bearing are used and
- Mono in case only one is used.

Besides selecting the configuration, the right probe channels need to be assigned to Y and X positions as well and their angle and direction need to be set.

The same needs to be done for the Keyphasor under the Tacho angle.

100			
	Setup		
D	Bearing properties		
Ť	Bearing name		
J	Bearing 1		
l			
I			
1	Configuration	Tacho angle	
1	Pair 🗸	✓ Left ✓ at 0 °	
1	Y position	X position	
1	Probe Y 🛛 🗸	Probe X ~	
1	Y angle	X angle	
1	Left $\checkmark$ at 45	° Right ∨ at 45 °	
1	Left <sup>0°</sup>	° Right	
ľ	- i		
ł			
	×		
I			
I			
I			
	190	0.0	
	180	J-	

Dewesoft Orbit Analysis supports extraction of subsynchronous orbit which can be used to detect fluid-induced instabilities such as whirl & whip. The calculation of the subsynchronous orbit is enabled via a dedicated checkbox and tracking filter bandwidth is defined in the corresponding input field:

Configuration		Tacho ang	le	
Pair	$\sim$	Left	$\sim$ at	• 0
Y position		X position		
Probe Y	$\sim$	Probe X		$\sim$
Y angle		X angle		
Left $\checkmark$ at 45	۰	Right	$\sim {\rm at}$	45 °
Left	0°	Right		
-		•		
Calculate subsynchr	× 180° onous orb	) Nit		
Tracking filter bandwidt	h			
10 Hz				

#### **Runout compensation**

Runout compensation is necessary whenever shaft irregularities in shape are present which could be misinterpreted as movement during the measurement. Dewesoft OA supports multiple ways of establishing the runout compensation:

1.) Paste - allows the user to paste values for runout compensation from previous measurements. The angle step needs to be defined the same in the Ch. setup as it was for the data that will be pasted and the data structure of the columns needs to be as stated below in the Import paragraph.

2.) Import - allows import of .txt files containing the runout compensation data. The data structure is important as it needs

to contain an angle in the first column, a Y value in the second, and X in the third. A good way to achieve correct structure is to input it in separate columns in Microsoft Excel and then save it as a .txt file. Example .txt file is seen below:

🦲 ru	//////////////////////////////////////				_	$\times$
File Ec	lit Format View	Help				
10 20 30 40 50 60 70	-1,02 1,54 1,29 -1,06 -1,27 0,49 0,86	1,69 1,16 -1,36 -1,36 0,73 1,06 -0,32				^

3.) Measure - The last and perhaps most important way of determining the runout compensation is to measure it directly with Dewesoft. This is also the easiest way of doing it as it requires a single click operation in Measure and calculated values are automatically stored in the Ch. setup.

#### Shaft

This section of channel setup is dedicated to the configuration of shaft-related settings. The direction of shaft rotation is selected in the Rotation dropdown. The drop-down allows the user to select between CW - clockwise direction and CCW - counterclockwise direction.

Shaft		
Rotation		Position
CW	~	Center ~
Average orbit		Bottom Top
Periods	Avera	Center

The Position dropdown defines the starting position of the shaft regarding the diameter of the bearing.

#### Clearance

Dewesoft Orbit Analysis supports a straightforward definition of the clearance circle under the Clearance section of the Machine Configuration Setup.

Users can select between Circle and Ellipse shapes for the clearance circle and use the input field to input the clearance circle Radius (circle) or Width & Height (ellipse).

Clearance		Clearance		
Shape	Radius	Shape	Width	Height
Circle 🗸	5 -	Ellipse 🗸	5 -	0 -

The average orbit can be configured to show more than a single revolution at once. This is defined by the input value in the field Periods - 5 periods means the average orbit will show 5 revolutions.

The user also defines the number of averages to take into the calculation of the average orbit by inputting the desired number into the Averages input field.

#### DC gap

Besides measuring and automatically compensating for the DC gap, Dewesoft Orbit Analysis allows the user to manually input the DC gap values.

This is especially useful with large turbines as seen in power plants where completely static conditions with 0 RPM are rarely seen. In such cases, the DC gap was measured upon mounting the probes and is manually input for later measurements.

### Reporting

- Monitoring and alarms
- Data output streaming to 3rd party system
- Report generation

### Orbit analysis output channels

In total, the Orbit analysis module contains many different result types of which many of the types will generate multiple channel results. The full list of output results from the Orbit analysis module, including a small description, of how many of such types will be created, and which display widgets to use for illustration, are all listed in the table below:

Function type	Description	Number of channels	Display widget
Orbit [X] X	[X] order orbit showing displacement in two directions	Per bearing, per order	Orbit plot
r[X]+	Positive-sided component of [X] order	Per bearing, per order	Digital meter
r[X]-	Negative sided component of [X] order	Per bearing, per order	Digital meter
G[X]	[X] order orbit ellipse semi- major axis, a	Per bearing, per order	Digital meter
κ[x]	[X] order orbit ellipse semi- minor axis, b	Per bearing, per order	Digital meter
Shaft center	Bearing shaft center displacement	Per bearing, per direction	Orbit plot
Raw orbit	Orbit with all orders over time	Per bearing	Recorder, scope
Bearing [X] Raw orbit	Orbit with all orders over time, with angle info for bearing [X]	Per bearing	Orbit plot
Average orbit	Orbit with all orders averaged over a number of blocks	Per bearing	Orbit plot, 2D graph
Bearing [X] waveform	Waveform with all orders of probe X or Y over time or revolutions	Per bearing, per probe	Orbit waveform
Subsynchronous orbit	Oil whirl/whip orbit	Per bearing	Orbit plot
Subsynchronous order	Oil whirl/whip variable fractional order number	Per bearing	Digital meter
DC gap	Probe DC gap over time	Per bearing, per probe	Digital meter
Time [X]X	[X] order data over time	Per bearing, per probe, per order	Recorder, digital meter
Polar [X]X	[X] order data with RPM stamps	Per bearing, per direction, per probe, and per order	Polar plot
Order waterfall vs. speed [two-sided]	Two-sided order spectra across the RPM speed range	Per bearing, per direction*, and per probe	3D graph
Order waterfall vs. time [two- sided]	Two-sided order spectra over time	Per bearing, per direction*, and per probe	2D graph, 3D graph
FFT waterfall vs. speed [two- sided]	Two-sided FFT spectra across the RPM speed range	Per bearing, per direction*, and per probe	3D graph
Order waterfall vs. speed	Order spectra across the RPM speed range	Per bearing, per direction*, and per probe	3D graph
FFT waterfall vs. speed	FFT spectra across the RPM speed range	Per bearing, per direction*, and per probe	3D graph
Bode plot [X]X	[X] order bode showing magnitude and phase vs. RPM speed	Per bearing, per direction*, and per probe	2D graph
Overall RMS	Total RMS value across the RPM speed range	Per bearing, per direction*, and per probe	2D graph
Overall peak	Total peak value across the RPM speed range	Per bearing, per direction*, and per probe	2D graph
Overall peal-peak	Total pk-pk value across the RPM speed range	Per bearing, per direction*, and per probe	2D graph

SPP Average orbit SPPy	Average orbit longest y direction pk-pk displacement	Per bearing	Digital meter
SPP Average orbit SPPx	Average orbit longest x direction pk-pk displacement	Per bearing	Digital meter
SPP Average orbit SPPmax	Average orbit longest overall pk-pk displacement	Per bearing	Digital meter
SPP Raw orbit SPPy	Raw orbit longest y direction pk-pk displacement	Per bearing	Recorder, digital meter
SPP Raw orbit SPPx	Raw orbit longest x direction pk-pk displacement	Per bearing	Recorder, digital meter
SPP Raw orbit SPPmax	Raw orbit longest overall pk- pk displacement	Per bearing	Recorder, digital meter
SPP orbit [X]X SPPy	[X] order orbit longest y direction pk-pk displacement	Per bearing, per order	Digital meter
SPP orbit [X]X SPPx	[X] order orbit longest x direction pk-pk displacement	Per bearing, per order	Digital meter
SPP orbit [X]X SPPmax	[X] order orbit longest overall pk-pk displacement	Per bearing, per order	Digital meter
Speed	Speed RPM for the OA instance	1	Digital meter
Direction	Test direction for the OA instance	1	Input control, Discrete display

per direction\* - is a user-selectable option with the checkbox "Separate spectra per direction".O

### Visualization - Orbit plot

Each bearing with assigned channels added to the machine train will automatically create a dedicated pre-defined display. On the predefined display, there will be a set of Orbit plots, Polar plots, and 2D graphs as well as a Digital meter for speed and an Input control dropdown to select between different operating conditions if Both are selected under RPM setup.

### Orbit plot

The Orbit plot is a specific widget for the Orbit Analysis module. The plot shows data from two time domain channels, plotting a two-dimensional visual picture of the motion of a rotating shaft.

The widget shows graphically the position of the proximity probes together with the tacho (keyphasor) position and direction of rotation.

There are different output channels available in the Orbit Analysis module that can be shown on the Orbit plot:

- Raw orbit,
- Average orbit,
- Filtered orbit (e.g. Orbit H1, Orbit H1, …),
- Subsynchronous orbit and
- Shaft centerline



When the Orbit Plot widget is selected, on the left side of the Measure display a tab of settings is available for the configuration of the axis to the user:

⊗ Axis		
Number of ticks	5	
Auto scale	0	5
Auto scale type	Absolute \	/
Single axis	Q	5

**Number of ticks** - changing the number of ticks will increase them on the Orbit plot accordingly. The left picture below shows 5 ticks and the right picture shows 15 ticks:



Auto scale - ticking the checkbox will automatically scale the axes of the Orbit plot. There are two different Auto scale types: Absolute and Relative.

• Absolute auto-scale always keeps the zero in the center of the plot and therefore gives a better indication of orbit size and position relative to the center of the bearing:



• Relative auto-scale sizes the axes according to the maximum current dimension of the measured orbit. This makes the orbit shape easier to observe and acts as a sort of zoom. The zero in this case is not always in the center position:


Single axis - this checkbox determines the behavior of how channel names are shown next to the orbit plot when showing multiple channels on the same graph. In the below example, two harmonic orbits are shown on the same orbit plot. The left image shows a single axis switched on and the right image shows a single axis switched off:



Besides axis configuration, there are different Drawing Options available when the Orbit plot widget is selected:

⊘ Drawing options						
Graph type	Grid	~				
Display type	RPM	$\sim$				
Clearance		$\odot$				
Color						
History type	Revolutions	$\sim$				
Revolutions	1					
Show only last position		0				

**Graph type** - The user can select either Grid or Circle. The difference between the two graph types is shown below - the left image shows a Grid and the right image shows a Circle:



When Circle is selected as Graph type, only Absolute auto scale will be available.

The selected Graph type is applied to all of the Orbit plots in the individual display in order to unify the visual representation of the particular display.

**Display type** - The user has the option to select either RPM or Time (in seconds) to be displayed when the Shaft center is assigned to the Orbit plot. The below images show the difference, the left image displays RPM and the right image displays Time together with the shaft center points:



Time Display type shows relative time - elapsed time since the beginning of the measurement

In the pictures below the relation between probe locations and the shaft location is illustrated. The orbit plot widget illustrates how four different locations will be plotted. In location 1 the black shaft is more distant from the proximity probes than in location 3:



In the picture below 6 orbit plots are shown for 6 different bearings. This can help with understanding the relationship of the keyphasor dot positions between bearing locations and hereby also to better understand the deflection shape of the rotor shaft.



## Visualization - Raw orbit

Raw orbit, also called Direct orbit, directly plots scaled time-domain data from a pair of orthogonal probes mounted at the same axial position on the rotating machine.

Raw orbit channel group can be displayed on the Orbit plot .



To plot the raw orbit using the Orbit plot widget you should select the Raw orbit channel group from the channel list. The Raw orbit channel group is located under the Bearing name level.

## Visualization - Average orbit

The 2D graph widget supports multi-trace and multigraph display of data meaning the average orbit can be shown both ways on the 2D graph.

Average orbits from different bearings can be displayed on the Orbit Plot in multigraph mode.

Average orbits from two bearings positioned closely along the shaft length displayed in multi-graph mode on Orbit Plot:



Average orbits from two bearings positioned closely along the shaft length displayed in multi-trace mode on 2D graph:



Average orbits from two bearings positioned closely along the shaft length displayed in multi-graph mode on 2D graph:



## Visualization - Filtered orbit

Filtered orbit, also called harmonic orbit, represents the extracted orbit of the order that has been input by the user in the Harmonic list section of the Calculation setup.

For each harmonic entered into the harmonic list, a separate channel is created:



Each created Filtered orbit channel data can be displayed on the Orbit Plot widget. As with Raw orbit and Average orbit, the Filtered orbit can be shown in multi-trace and multigraph modes.

Filtered orbits H1-H4 displayed in multi-trace mode on Orbit plot:



Filtered orbits H1-H4 displayed in multi-graph mode on Orbit plot:



## Examples of 1X and Subsynchronous Orbits

The orbit at the left shows subsynchronous fluid-induced instability. Note the multiple key phasor dots because the frequency is not a fraction of the running speed.

The orbit at the right is predominantly 1X. The key phasor dots appear in a small cluster indicating dominant 1X behavior



# Visualization - Polar plot

Polar plot is a dedicated widget, featured in the Dewesoft Orbit Analysis module. It allows representation of Amplitude, Phase and Speed together with the shaft center on the same display for a comprehensive, single widget overview of the machine operation.

Each probe has a set of dedicated, corresponding polar plots for each order of extracted filtered/harmonic orbit. The polar plots for runup, coastdown and steady state are written into separate channels, depending on the selection of the dropdown Input control, Output channels and visual representation.

The predefined Orbit analysis measurement display comes with a Polar plot widget for each of the used probes per bearing. When using OA with a pair of probes this means a pair of Polar plots is autogenerated and each one represents data from one of the probes - Y and X.



# Visualization - Orbit waveform graph

The Orbit waveform graph widget plots bearing X and Y sensor displacement data across a user-defined time duration or across a specific number of revolutions.

Each new tacho key phaser crossing is indicated with a dot in the graph as illustrated below:



When a fixed time duration is selected, then the number of revolutions varies as time goes on, as illustrated above.

A fixed time duration can be selected by setting the History type parameter to Time. You can determine the time duration (Display time) shown in the graph.

If the History type is set to Revolutions then you can select the number of Revolutions you want plotted.



With the History type set to Revolutions, you also have the option to either have an axis with a fixed Revolution count or Angle, or to have a variating Time length on the axis that changes as the revolution speed changes, such that the number of plotted revolutions are kept constant.

# Typical display for Orbit analysis

Throughout the years of Orbit Analysis evolution, there was a set of display layout designs developed that are typical for the application. As Dewesoft offers advanced customization possibilities it is easy to create, edit, and transform the typical display layouts within a few clicks. In the following sections, you will find examples of how to generate such display layout templates.

## Raw orbit with clearance circle

Created by assigning the Raw Orbit channel group to the Orbit Plot widget and switching the clearance circle option on the left side widget settings. Clearance circle needs to be defined beforehand in the Orbit Analysis channel setup.



# Full motion graph

Created from Raw orbit with Clearance circle by adding the Shaft center channel to the Orbit plot. In other words, it is created by assigning the Raw orbit and Shaft center to the Polar plot widget and switching on the Clearance circle. Clearance circle needs to be defined beforehand in the Orbit Analysis channel setup.



## Runout compensation display

Runout compensation, sometimes called slow-roll compensation, is applied to compensate for any shaft irregularities (flattenings or other variations in diameter along the circumference variations) that would have otherwise been picked up by the proximity probes together with the actual movement of the shaft.

After it has been set up in the Ch. setup, the compensation itself is performed through a dedicated measurement display, that is generated automatically together with predefined Overviews for each Bearing and and a Reference Orbit display.



The predefined Runout compensation display consists of the following elements:

- 1. 1. Recorder with raw signals from proximity probes
- 2. 2. Start button to initiate the runout compensation
- 3. 3. Measurement status
- 4. 4. Current speed of the machine



Upon starting the measurement, the status in the measurement status bar switches from Ready to displaying the measurement progress. The measurement itself takes the number of averages that were user-defined in the Ch. setup section under Runout compensation.

	OA 1/Averaging status ACT	OA 1/Speed (RPM) ACT
Start	In progress. Average: 12/40	303.4

The system displays the status Done after the measurement of runout compensation has been completed successfully:

	OA 1/Averaging status ACT	OA 1/Speed (RPM) ACT
Start	Done	300.0

After the Runout compensation measurement is Done,, the calculated values are automatically added to the setup and can be seen under Ch. setup under the Machine configuration - Bearing Setup page:

Setup											×
Bearing properties											
Bearing name Bearing 1											
Sensors											
Configuration	Tacho angle			Runout	t compensation	~	Add	Remove	Paste	Import	Export
Pair ~	Left v at 0	•			[9] alcole		V Imm	1		V [mm]	1
Y position	X position			_	Angel J	-	- (mi)	1		v finnil	- 1
Probe Y V	Probe X	~			0,00		-3,12			4,01	
Y angle	X angle				1,00		-2,98			4,44	
Left v at 45	Right V at 45	_			2,00		-2,93			4,80	
Left 0°	Right				3,00		-2,94			5,04	
	-				4,00		-3,00			5,42	
-					5,00		-3,14			5,80	
					6,00		-2,94			6,04	_
					7,00		-2,83			6,17	
					8,00	-	-2,90			6,35	
					9.00		-2.73			6.54	_
180°					10.00	-	-2.53			6.72	
Calculate subsynchronous of Translates filters benchrighth	orbit				20,00		-2,00			6,72	
F He					11,00		-2,30			0,90	_
5 MZ					12,00		-2,30			7,27	
Shaft		Clearance				DC 6	ap				
Rotation Pos	ition	Shape	Radius			Sens	or Y	Sen	sor X		
CW V Ce	nter 🗸	Orde V	20	mm		0		mm 0		mm	
Average orbit		Channel colors									
Periods Averages		Runup	Steady :	state	Coastdown						
3 3	_	•			•						
										_	
									OK		Cancel

In case the Runout compensation display needs to be manually added, this is done through the following steps:

- 1. 1. Select Displays
- 2. 2. Select + the button
- 3. 3. (Optionally) Go to the Add sub-display tab
- 4. 4. Select Runout compensation

ulate	E Save	<b>D</b> esign	Widgets	Displays	26.3 Recorder	26.3 Custom	26.3 04.1	26.3 Function g	26.3 Order trac	
		▲ Manage	displays	Θ	_J.	)				
2		Recorder Custom ▼ OA 1 Bearing Runout	1 overview compensatio	n	Display prop Display nan Runout co Icon	erties ne mpensation	_			
		Reference Orbit Function generator Order tracking		🔺 Add d	lisplay		٩	Add display	Add subdisplay	у
				General				0A 1		
				Custom				All		8
				Overview				Bearing 1 over	view	
				Recorder				Bearing 1 wav	eforms	
				Overload				Runout compe	ensation 🗡	6
				Function	generator			Reference Orb	it	

If you need to update OA display templates then right-click on the relevant display tab or sub-display and select Rebuild.



# Recalculation of stored data

Orbit analysis can be recalculated using the raw signals from the proximity probes and the frequency source that has been stored during the measurement. To recalculate data simply open the datafile with the raw signals included and in Analyze mode navigate to Offline math:



1. When in Setup, add the Orbit Analysis by selecting Moreâ€; and choosing Orbit Analysis from the list of modules:



- 2. Having added the Orbit Analysis module, configure it by following the same steps described in the previous sections.
- 3. Return to Review and select Recalculate



4. The recalculated output channels are now displayed on the predefined display.

If you see an Offline math button instead of the Recalculate button, then go to Setup and set the Orbit analysis module to Offline.



## Recalculating Runout correction

Together with all of the output channels from Orbit Analysis, Runout compensation can also be recalculated in postprocessing using the raw data from the proximity probes.

To recalculate and apply runout compensation in Analyze mode, please follow the steps below:

1. Navigate to the Runout compensation sub-display template.



2. In the Runout compensation display, place the two cursors over the section of raw data you wish to use for the runout compensation and lock them.



3. Click on Recalculate to determine the runout compensation data:



If you see an Offline math button instead of the Recalculate button then set the Orbit analysis module to Offline first under Setup.

4. After Recalculation, the calculated values are automatically added to the setup and can be seen under the Machine configuration - Bearing Setup page:

Setup							×
Bearing properties							
Bearing name							
Bearing 1							
Configuration Tacho socia		_					
Dair V Left V at 0	•	Ru	nout compensation	<ul> <li>✓ Add</li> </ul>	Remove	Paste Import	Export
	_		Angle[°]	Y [mr	n]	X [mm]	
Prohe V V Prohe X	<u> </u>		0.00	-3.1	2	4.01	_
V socia			1.00	-7.9	-	4 44	_
left ∨ at 45 ° Rinht ∨ at 45	•		2,00	2,5	5	4.90	_
Lett be to hight be to	_		2,00	-2,9	2	4,00	_
Left Right			3,00	-2,9	4	5,04	_
			4,00	-3,0	0	5,42	
			5,00	-3,1	4	5,80	
×			6,00	-2,9	4	6,04	
			7,00	-2,8	3	6,17	
			8,00	-2,9	D	6,35	
			9,00	-2,7	3	6,54	_
180°			10,00	-2,5	3	6,72	
Tracking filter bandwidth			11.00	-2,3	3	6,98	_
5 Hz			12,00	-2,3	D	7,27	
Shaft	Clearance			DC Gap		1	
Rotation Position	Shape	Radius		Sensor Y	Ser	isor X	
CW V Center V	Cirde 🗸	20 n	nm	0	mm 0	mm	
Average orbit	Channel colors		C and here				
Periods Averages	Runup	Steady state	Coastdown				
<u> </u>	_		-				
						ОК	Cancel

Make sure to save the setup after measuring the runout compensation in order to be able to simply load and have it ready the next time you use the setup

## Recalculating reference orbit

From acquired raw data it is possible to define the reference orbit also in Analyze mode. To recalculate and store the reference orbit in Analyze mode, please follow the below steps:

1. Navigate to the pre-defined Reference orbit sub-display template:

26.3
OA 1
26.3 Bearing 1
26.3 Runout compensation
26.3 Reference Orbit

2. Place the two cursors over the desired region from which you wish to acquire data to define the Reference orbit, and then lock the cursors:



3. Select Recalculate. If you see an Offline math button instead of the Recalculate button then set the Orbit analysis module to Offline first under Setup.

4. Now the newly calculated Reference orbit data are copied to the clipboard and can be pasted directly into a Reference orbit data table found under the Bearing Setup page.

# Machine fault - normal operation

Normal operation is indicated by acceptable vibration at all measurement positions. Critical speeds may be excited during speed transients, but the amplitude will be acceptable. Trend plots show constant amplitude with little or no variation with load. The dominant vibration frequency is 1X with little or no vibration at any other frequencies.

# Amplitude trend

The amplitude trend plot indicates constant amplitude with no significant load or time dependency.

# 1X phase trend

1X phase trend will show a constant phase value over time.

# Waveform

Direct waveform plots show no truncation, frequencies other than 1X, or spikes.

## Spectrum

1	x		
		~~~~~	

The half-spectrum plot shows one dominant peak at 1X frequency with no significant vibration at other frequencies.

# Full spectrum / Two-sided spectrum



The full spectrum plot shows one dominant positive peak at +1x frequency with no significant vibration at other frequencies. Peak at -1X is lower than +1X.



Direct orbit



Circular or slightly elliptical orbit with no evidence of truncation or loops. Phase trigger indicates forward precession.



The shaft centerline plot shows the normal path from zero to full speed with no sudden changes. Eccentricity remains below the vertical centerline at full speed.

## Bode plot amplitude

۸.	Startup	vn.
	Coastuov	***

The bode plot (amplitude) shows acceptable amplitude at a critical speed. Some variation between startup and coastdown responses is typical.



The bode plot (phase) shows a smooth phase shift through typical speed, with the rate of change matching previous runup or coastdown events. The phase at full speed and very low speed is consistent between events.

#### Polar plot



The polar plot shows similar amplitude at low speed, through critical speed, and at full speed between transient events with acceptable maximum amplitude at critical speed and at full speed.



The waterfall plot will show fairly constant amplitude through multiple periods with no significant variation in the 1X amplitude.

# Other operational symptoms

Bearing temperature trends are constant with speed and load and below alarm limits. The audible noise near the machine does not indicate any changes from previous surveys or any abnormal rattling.

# Waterfall

# Machine fault - Mechanical imbalance (blade loss)

A sudden imbalance may be caused by a blade loss, loss of balance weight, or another component normally attached to the rotor. This may occur during normal operation or a load or speed transient. It can be differentiated from an electrically induced imbalance because the changes in vibration characteristics (amplitude/phase) are not reversible by changing load or speed.



Vibration amplitude trends show a sudden increase in amplitude. Similar step changes may be noted in vibration phase trends.

## 1X phase trend



1X phase trend will show a step change. The phase may increase or decrease depending on the angle between the location of the lost material and the residual unbalanced vector.

# Waveform



The direct waveform plot (at the time of damage) will show a sudden increase in amplitude. If the amplitude is excessive, some truncation may be present.

#### Spectrum

1X	Before event After event

After the event, the half spectrum will show an increase n 1X amplitude compared to before the event. Some smallamplitude peaks at n-X frequencies may be present.

## Full spectrum / Two-sided spectrum

Before event After event			1	x	
	-1X				

The full spectrum plot will show an increase in both +1X and -1X peaks. There may be some increase at +/- n-X frequencies. The +1X will be higher than the -1X peak unless another fault is present.

The direction of shaft precession is indicated by a dominant line of "CCW†and "CW†components.

- $\hat{a}$   $\in$  How flat the ellipse will be is determined by the relative size of CCW and CW components
- $\hat{a}$  €¢ When the orbit is circular there is only one spectrum line
- $\hat{a}$  €¢ When the orbit is a line the CCW and CW spectrum components are equal
- $\hat{a} \in c$  The smaller the difference between components, the more elliptical the orbit.



Direct orbit



Direct orbit plot will show an increase in amplitude as well as a phase change before and after the event indicated by a change in the position of the phase trigger marker.

# Shaft centerline



The shaft centerline plot will normally show a jump in position immediately after the event, and the shaft will return to near the pre-event position shortly after.

#### Bode plot - amplitude



The bode plot (amplitude) will show an increase in amplitude at all speeds after a blade loss. Critical speed will not change, and the amplification factor should be approximately the same as before the event.

## Bode plot - phase

		Before ev After evei	ent nt

The bode plot (phase) will show a constant phase shift from before and after the event that is constant at all speeds.

Polar plot



The polar plot shows an amplitude increase and a phase shift after the event. The phase shift will be constant at all speeds.

# Waterfall

	а	
Time		
x		

The waterfall plot will show a step change in the 1X amplitude after the event occurs.

#### Other operational symptoms

The increase in vibration amplitude caused by sudden unbalance may result in an increase in bearing metal temperature. If the lost component becomes lodged in the turbine, the noise may increase as indicated by rattling or broadband noise due to flow disturbances.

# Machine fault - Misalignment

Misalignment will generally result in elevated vibration amplitude due to load transfer from one bearing to an adjacent bearing. The increase will show up as higher amplitude at 1X and 2X in spectrum plots, with 2X amplitude reaching or exceeding 1X amplitude as the severity of the misalignment increases. The misalignment may be coupling or internal misalignment caused by improper bearing elevations.

# Amplitude trend

Vibration amplitude trend plots will show increased amplitude in the presence of excessive misalignment.

## 1X phase trend

1X phase trend will generally be unaffected by misalignment.

## Waveform



Misalignment will often result in a 2X response. This will be apparent in the direct waveform plot with an increase in peakto-peak amplitude and 2X frequency component.

#### Spectrum

1X				
		2X		

The half-spectrum plot will show elevated 2X vibration in the presence of misalignment. The relative amplitude of the 1X and 2X peaks is indicative of the severity of the misalignment.

## Full spectrum



The full spectrum plot will show an increase in the +/- 1X and +/- 2X peaks. The positive peaks will generally be higher than the negative peaks.



Direct orbit plot will show evidence of the constrained shaft motion from the misalignment. More severe misalignment may result in an orbit resembling a banana or even a figure-eight shape.

### Shaft centerline



Misalignment may result in a shaft centerline plot that shows the rotor position farther away from the bearing center. This would be dependent on the severity of the misalignment.
An amplitude bode plot will generally be unaffected by misalignment, other than an increase in amplitude at all speeds over a properly aligned machine.

# Bode plot - phase

The phase of the bode plot will be unaffected by misalignment.

# Polar plot

A polar plot will generally be unaffected by the misalignment other than an increase in amplitude at all speeds over a properly aligned machine.

#### Waterfall



Waterfall plot vs. time will show elevated 1X and 2X vibration in the presence of misalignment. The relative amplitude of the 1X and 2X peaks is indicative of the severity of the misalignment.

# Other operational symptoms

Elevated bearing metal temperatures, combined with higher 1X and 2X orders of vibration can be a strong indicator of misalignment. The elevated bearing temperature may be caused by both the higher vibration amplitude and the increased static load reacted by the bearing in the presence of misalignment.

# Machine fault - oil whirl

Oil whirl is normally caused by improper design of the rotor-bearing system. The presence of vibration components at frequencies slightly less than 1/2X with varying amplitude are indications of oil whirl. Oil whirl can be aggravated by higher speed, higher oil viscosity, and lighter bearing loading.

# Amplitude trend

The overall amplitude trend will normally show a high average amplitude with large variations in the presence of oil whirl.

# 1X phase trend

The 1X phase trend will generally be stable with constant speed in the presence of the oil whirl.

### Waveform



The time waveform plot will show both 1X vibration and a subsynchronous component near 0.48X with an amplitude that varies over time

#### Spectrum

		1X		
0.48X				

The half spectrum will show a 1X peak and a peak slightly below 1/2X that will normally vary in amplitude over time.



The full spectrum plot will show forward precession and a subsynchronous peak at slightly less than 1/2X.



The direct orbit plot will show the 1X and the slightly less than 1/2X components. The phase marker will slowly shift in the direction opposite rotation, but the vibration precession will remain forward.

### Shaft centerline

The shaft centerline position will generally be unaffected by the oil whirl, however, operation near the bearing centerline will be more susceptible to oil shirl

# Bode plot - amplitude

The amplitude plot will generally be unaffected by the oil whirl.

#### Bode plot - phase

The phase will generally be unaffected by the oil whirl.

# Polar plot

Polar plot will generally be unaffected by the oil whirl.



A cascade plot will show the onset of instability with a subsynchronous peak showing up at a frequency slightly less than 1/2X.

# Other operational symptoms

Oil whirl vibration may be affected by changing the lube oil supply temperature. This has the effect of changing the rotor dynamic coefficients of the bearing. These changes have a limited impact on whirl vibration.

# Machine fault - oil whip

Oil Whirl will transition to Oil Whip when the whirl frequency reaches the first natural frequency.

The sub-synchronous vibration will lock onto the unstable natural frequency and will not continue to increase with the rotor speed. The sub-synchronous vibration will increase and can be damaging.

# Amplitude trend

The overall amplitude trend will show very high amplitude in the presence of a whip. The amplitude may increase until a limit cycle is reached.

# 1X phase trend

The 1X phase trend will generally be stable with constant speed in the presence of the oil whip.

#### Waveform

The time waveform plot will show both 1X vibration and a subsynchronous component at the unstable natural frequency.

#### Spectrum

Fn				
		1	.X	

#### Full spectrum



The full spectrum plot will show elevated +/- 1X and very high subsynchronous vibration at the unstable natural frequency.

#### Direct orbit



The amplitude in the direct orbit will grow after the transition from whirl to whip. The precession will remain forward, and

the phase marker will continuously shift in the direction opposite rotation at a faster rate.

#### Shaft centerline

The shaft centerline position will normally be unaffected by oil whip except that operation near the bearing centerline will be more susceptible to oil whirl.

# Bode plot - amplitude

A bode plot - amplitude, will generally be unaffected by oil whip.

# Bode plot - phase

A bode plot - phase will generally be unaffected by oil whip.

### Polar plot

A polar plot will generally be unaffected by oil whip.

#### Waterfall



A waterfall plot will appear similar to an oil whirl until the transition to whip. The subsynchronous vibration frequency will

# Other operational symptoms

Oil ship will be extremely destructive to the turbine generator. The vibration amplitude will generally grow over time.

# Machine fault - operation on resonance

Operating a turbine generator on a critical speed or a structural resonance will result in an elevated 1X vibration amplitude. This is normally the result of a design deficiency but can also be caused by changes to the system that cause shaft critical speeds to shift, or structural issues, such as foundation degradation, that result in changes to structural natural frequencies.

### Amplitude trend

The overall and 1X amplitude trend plot will show elevated but constant amplitude with constant speed then running at resonance.

# 1X phase trend

The 1X phase trend will be unaffected by operation on resonance at constant speed.

### Waveform

The time waveform will show an elevated 1X amplitude.

#### Spectrum

1X		

The half-spectrum plot will show a high amplitude at 1X when operating at resonance.

### Full spectrum

	+1X		
-1X			

The full spectrum plot will show elevated +1X amplitude. The -1X amplitude will depend on the ellipticity of the orbit plot.

#### Direct orbit



The direct orbit plot will show forward precession with elevated amplitude.

# Shaft centerline



The shaft centerline position will generally not be useful in diagnosis operation on resonance.





The Bode plot (amplitude) will show elevated amplitude at the operating speed.

#### Bode plot - phase

The Bode plot (phase) will show a phase shift as the operating speed is approached.



A polar plot will show the phase shifting and the amplitude peaking as the operational speed is approached.

#### Waterfall



A waterfall plot will show the 1X peak increasing in amplitude as the operating speed is approached.

# Other operational symptoms

Measurement from seismic instrumentation can help to confirm operation on resonance. If the machine has not previously operated on resonance, changes to foundation stiffness or bearing clearance may cause the structural natural frequencies or rotor bearing critical speeds to shift into the operating speed range and will require correction.

# Radial load effect on orbit shape

The orbit plots below are from two different shaft scenarios with opposite rotation.

Both shafts are experiencing high radial loads. Orange arrows indicate the approximate direction of the applied radial load and orange arcs represent a part of the bearing wall.

